

References

- Ahmed-Zeki, A. S., N. Logan, (2000). Monitoring the Cut-Off Wall Performance of Upper Huia Dam. *Geotechnical Special Publication No. 94*, ASCE, 212-227.
- AMEC (2004). Seepage Analysis Wolf Creek Dam, Cumberland River, Jamestown, Kentucky, AMEC Earth and Environmental, Inc., Nashville, Tennessee.
- Anton, W. F. and D. J. Dayton (1972). Camanche Dike-2 Slurry Trench Seepage Cutoff. *Proceedings of the Specialty Conference on the Performance of Earth and Earth-Supported Structures*. Purdue University, ASCE, 735-749.
- Bechtel (1967). As-Built Construction Plans for Comanche Dike-2 Seepage Control, Bechtel Corporation, prepared for East Bay Municipal Utilities District.
- Bellport, B. P. (1967). Bureau of Reclamation's Experience in Stabilizing Embankment of Fontenelle Earth Dam. *International Committee on Large Dams, Ninth International Congress on Large Dams*, Istanbul, Turkey, 67-79..
- Bradley, J., D. Bruce, K. Ferguson, S. Poulos, J. Talbot, J. Vrymoed (2007). Wolf Creek Dam Consensus Report, Engineering Risk and Reliability Analysis, Submitted to Headquarters, United States Army Corps of Engineers.
- Breek, H. C. M. (1992). Construction of 'Thin' Slurry Walls and the Supporting Liquid Slurries Used. *Construction and Quality Control, Special Technical Publication No. 1129*, ASTM, 324-332.
- Britton, J. P. and G. M. Filz (2006). Closure to "Measuring the Hydraulic Conductivity of Soil-Bentonite Backfill" by Jeremy P. Britton, George M. Filz, and Wayne E. Herring. *Journal of Geotechnical and Geoenvironmental Engineering*, ASCE, 132(6): 812-814.
- Britton, J. P., G. M. Filz, and W. E. Herring (2004). Measuring the Hydraulic Conductivity of Soil-Bentonite Backfill. *Journal of Geotechnical and Geoenvironmental Engineering*, ASCE, 130(12): 1250-1258.
- Britton, J. P., G. M. Filz, and J.C. Little (2005). The Effect of Variability in Hydraulic Conductivity on Contaminant Transport Through Soil-Bentonite Cutoff Walls. *Journal of Geotechnical and Geoenvironmental Engineering*, ASCE, 131(8): 951-957.
- Britton, J. P. (2001). Soil-Bentonite Cutoff Walls: Hydraulic Conductivity and Contaminant Transport. Ph.D Dissertation, Virginia Polytechnic Institute and State University. Blacksburg, Va.
- Bruce, D. A. and S. Stefani (1996). Rehabilitation of Beaver Dam: a Major Seepage Cut-Off Wall. *Ground Engineering*, 29(5): 40-45.

- Bryan, J. (1987). Concrete Cutoff Wall through Earth Embankments at Walter F. George Dam. *Association of Engineering Geologists 30th Annual Meeting*, 30, 35.
- CDWR (1916). Lower Franklin Dam (note to file), California Department of Water Resources.
- Cedergren, H. R. (1969). Camanche Reservoir, Study on Groundwater Spreading Below Dikes 1 and 2, Report to East Bay Municipal Utilities District, Sacramento, California.
- Clough, G. W. and J. M. Duncan (1969). Finite Element Analyses of Port Allen and Old River Locks. U. S, Army Eng Waterways Experiment Station, Corps Eng, Contract Rep TE 69-3 (S-69-6): 264.
- Coluzzi, A. A. (1972). Memorandum of Review of Hydraulic Fill Dam, Fairmont Dam, No. 6-8, September 1972, California Department of Water Resources, Division of Safety of Dams.
- Couch, F. B. (1977). Foundation Seepage Problems at Wolf Creek Dam. Proceedings *Ohio River Valley Soils Seminar*, Louisville, KY.
- Dames and Moore (1979). Test Filling of Reservoir Slumping Study, Lake Wolford Dam, Escondido, California, Prepared for Escondido Mutual Water Company, Dames & Moore Consultants.
- Davidson, L. (1990). Performance of the Concrete Diaphragm Wall at Navajo Dam. *Dam Foundation Engineering, Tenth Annual USCOLD Lecture*, New Orleans, Louisiana, U.S. Committee on Large Dams, 1-21.
- Davidson, R. R., G. Denise, B. Findlay, and R. Robertson (1992). Design and Construction of a Plastic Concrete Cutoff Wall for the Island Copper Mine. *Special Technical Publication No. 1129*, ASTM, 271-288.
- Davidson, R. R., J. Levallois, and K Graybeal (1992). Seepage Cutoff Wall for Mud Mountain Dam. *Special Technical Publication. No. 1129*, ASTM, 309-323.
- Dewey, R. (1988). Installation of a Deep Cutoff Wall at Navajo Dam. Proceedings *Sixteenth Congress on Large Dams*, International Commission on Large Dams, 5, 230-238.
- de Wit, J. B. Sellmeijer, and A. Penning (1981). Laboratory Tests on Piping. Proceedings *Tenth International Conference on Soil Mechanics and Foundation Engineering*, Stockholm, 517-520.
- DSOD (2004). Geologic Review of Updated Seismic Stability Evaluation, Cherry Flat Dam, No. 24, Santa Clara County, California Department of Water Resources, Division of Safety of Dams.

- Duncan, J. M., P.M. Byrne, K.S. Wong, and P. Mabry (1980). Strength, Stress-Strain, and Bulk Modulus Parameters for Finite Element Analyses of Stresses and Movements in Soil Masses. *Geotechnical Engineering Report No. UCB / GT / 80-01*, University of California at Berkeley.
- Duncan, J. M. and K. S. Wong (1999). User's Manual for SAGE, Volume II - Soil Properties Manual, Department of Civil Engineering, Virginia Polytechnic Institute and State University.
- Eckerlin, R. D. (1992). Mud Mountain Dam Concrete Cutoff Wall - A Case History. *Bulletin of the Association of Engineering Geologists XXIX*,(1), 11-32.
- Eckerlin, R. D. (1993). Mud Mountain Dam Concrete Cutoff Wall. Proceedings *Geotechnical Practice in Dam Rehabilitation, Geotechnical Special Publication No. 35*, ASCE, 284-298.
- Engle, G. F. (1933). Memo to Mr. Hawley, Cherry Flat Dam #24, Date of Inspection December 29 & 30, 1932, California Department of Water Resources.
- Erwin, E. D. and J. M. Glenn (1992). Plastic Concrete Slurry Wall for Wister Dam. *Special Technical Publication No. 1129*, ASTM, 251-267.
- Farrar, J. A., Wirkus, K.E., McClain, J.A. (1990). Foundation Treatment Methods for the Jackson Lake Dam Modificaiton. *Dam Foundation Engineering, Tenth USCOLD Lecture* New Orleans, Louisiana, U.S. Committee on Large Dams, 1-33.
- Fell, R., C. F. Wan, (2001). The Time for Development and Detectabilty of Internal Erosion and Piping on Embankment Dams and their Foundations, UNICIV Report No. R-399, The University of New South Wales.
- Fell, R., C. F. Wan, J. Cyganiewicz, and M. Foster (2003). "Time for Development of Internal Erosion and Piping in Embankment Dams." *Journal of Geotechnical and Geoenvironmental Engineering*, ASCE, 129(4), 307-314.
- Fell, R., C. F. Wan, and M. Foster (2004). Methods for Estimating the Probability of Failure of Embankment Dams by Internal Erosion and Piping - Piping Through the Embankment, UNICIV Report No. R428, The University of New South Wales.
- Fell, R. and C. F. Wan (2005). Methods for Estimating the Probability of Failure of Embankment Dams by Internal Erosion and Piping in the Foundation and from the Embankment to Foundation, UNICIV Report No. R436, The University of New South Wales.
- Fenoux, G. Y. (1985). Filling Materials for Watertight Cutoff Walls, *Bulletin 51*, International Committee on Large Dams.

- Fetzer, C. A. (1979). Wolf Creek Dam Em Dash Remedial Work Engineering Concepts, Actions and Results. *Technology Review*, v 2, 57-82.
- Filz, G. M., T. Adams, and R. R. Davidson (2004). Stability of Long Trenches in Sand Supported by Bentonite-Water Slurry. *Journal of Geotechnical and Geoenvironmental Engineering*, ASCE, 130(9), 915-921.
- Filz, G. M., L. B. Henry, G. M. Heslin, and R. R. Davidson (2001). Determining Hydraulic Conductivity of Soil-Bentonite Using the API Filter Press. *Geotechnical Testing Journal*, ASCE, 24(1), 61-71.
- Foster, M., R. Fell, and M. Spannagel (2000a). Statistics of Embankment Dam Failures and Accidents. *Canadian Geotechnical Journal*, 37(5), 1000-1024.
- Foster, M., R. Fell, M. Spannagel (2000b). Method for Assessing the Relative Likelihood of Failure of Embankment Dams by Piping. *Canadian Geotechnical Journal*, 37(5), 1025-1061.
- Foster, M. and R. Fell (2001). Assessing Embankment Dam Filters Which Do Not Satisfy Design Criteria. *Journal of Geotechnical and Geoenvironmental Engineering*, ASCE 127(4), 398-407.
- Foster, M. A., R. Fell, M. Spannagle (1998). Analysis of Embankment Dam Incidents, UNICIV Report No. R374, The University of New South Wales.
- Foster, M. A. and R. Fell (1999). Assessing Embankment Dam Filters Which Do Not Satisfy Design Criteria, UNICIV Report No. R-376, The University of New South Wales.
- Fox, P. J. (2004). Analytical Solutions for Stability of Slurry Trench. *Journal of Geotechnical and Geoenvironmental Engineering*, ASCE, 130(7), 749-758.
- Freeze, R. A. and J. A. Cherry (1979). *Groundwater*, Prentice-Hall, Inc.
- Gagliardi, J. and R. Routh (1993). Geotechnical Modifications at Meeks Cabin Dam. *Geotechnical Special Publication No. 35*, ASCE, 755-769.
- Garber, H. J. (1972). Memorandum of Review of Hydraulic Fill, Crane Valley Storage Dam and Reservoir, No. 95-3, California Department of Water Resources.
- Germanis, E. (1975). Stability of Hume Dam. Institution of Engineers, Australia, *Civil Engineering Transactions*, CE 17(2), 69-76.
- Gould, J. P. and H. S. Lacy (1993). Seepage Control in Dam Rehabilitation. *Geotechnical Practice in Dam Rehabilitation*, *Geotechnical Special Publication No. 35*, ASCE, 240-255.

- Holland, T. C., B. C. Gerwick, Jr., J. R. Turner (1982). Tremie Concrete Placement, Wolf Creek Dam Cutoff Wall. *Concrete International*, 4(10), 26-34.
- Kahl, T. W., Kauschinger, J.L., and Perry, E.B. (1991). Plastic Concrete Cutoff Walls for Earth Dams, United States Army Corps of Engineers, Technical Report REMR-GT-15, Waterways Experimentation Station, Vicksburg, MS.
- Khoury, M. A., P. H. Fayad, R. S. Ladd (1992). Design, Construction and Performance of a Soil-Bentonite Cutoff Wall Constructed in Two Stages. *Special Technical Publication. No. 1129*, ASTM, 289-308.
- LADWP (2001). Lower Franklin Dam and Reservoir, No. 06-14, Review and Evaluation of Performance (REP), January 1, 1992 to December 31, 2001, Report to California Department of Water Resources, Division of Safety of Dams, City of Los Angeles, Department of Water and Power
- Lee, T. and C. H. Benson (2000). Flow Past Bench-Scale Vertical Ground-Water Cutoff Walls. *Journal of Geotechnical and Geoenvironmental Engineering*, ASCE, 126(6) 511-520.
- Lefebvre, G., C. Lupien, J. J. Pare, and J. P. Tournier (1981). Effectiveness of Seepage Control Elements for Embankments on Semipervious Foundations. *Canadian Geotechnical Journal*, 18, 572-576.
- Leventon, H. L. (1930a). Memorandum to Mr. Hawley, Lower Franklin Dam No. 6-14, Inspected April 24, 1930, California Department of Water Resources.
- Leventon, H. L. (1930b). Memorandum to Mr. Hawley, Fairmont Dam No. 6-8, Inspected May 14, 1930, California Department of Water Resources.
- MACTEC (2004). Completion Report for Installation of Underground Concrete Cutoff Wall, Walter F. George Lock, Spillway, and Powerhouse, Prepared for the United States Army Corps of Engineers, Mobile District.
- Marsal, R. J. and D. Resendiz (1971). Effectiveness of Cutoffs in Earth Foundations and Abutments of Dams. Proceedings *4th Pan-American Conference on Soil Mechanics and Foundation Engineering*, State-of-the-Art-Paper, ASCE, 237-312.
- McAlexander, E. L. and W. O. Engemoen (1985). Designing and Monitoring for Seepage at Calamus Dam. In *Seepage and Leakage from Dams and Impoundments, Proceedings of a symposium in conjunction with the 1985 ASCE National Convention*, 183-199.
- McCook, D. (2004). A Comprehensive Discussion of Piping and Internal Erosion Failure Mechanisms. Proceedings: *The Annual Conference of the Association of State Dam Safety Officials, Dam Safety 2004*, September 26-30, 2004

- McFarland, D. (1930). Memorandum to Mr. Hawley, Lake Wolford Dam No. 834, Inspected February 10, 1930., California Division of Water Resources, Department of Public Works.
- McDonald L. and C. F. Wan (1999). Risk Assessment for Hume Dam - Lessons from Estimating the Chance of Failure. *Bulletin No. 112*, Australian National Committee on Large Dams, 1-14.
- Miedema, D. G. and J. A. Farrar (1988). History and Investigation of Jackson Lake Dam. *Geotechnical Special Publication No. 21*, ASCE, 902-923.
- Millet, R. A., J.-Y. Perez, and R. R. Davidson (1992). USA Practice Slurry Wall Specifications 10 Years Later. *Special Technical Publication. No. 1129*, ASTM, 42-66.
- Mitchell, J. K. and R. R. Rumer (1997). Waste Containment Barriers: Evaluation of the Technology. Proceedings, *In Situ Remediation of the Geoenvironment*, *Geotechnical Special Publication 71*, ASCE, 1-25.
- Murray, B. C. and S. E. Browning (1984). Unique Monitoring of Possible Recurring Foundation Problems at Fontenelle Dam. Proceedings: *International Conference on the Safety of Dams. Coimbra, Portugal*, 227-234.
- NJWSA (1992). 1992 Annual Inspection of the Dam and Dikes at the Manasquan Reservoir System., New Jersey Water Supply Authority.
- NJWSA (2000). 2000 Annual Inspection of the Dam and Dikes at the Manasquan Reservoir System0, New Jersey Water Supply Authority.
- NJWSA (2005). 2005 Annual Inspection of the Dam and Dikes at the Manasquan Reservoir System., New Jersey Water Supply Authority.
- NSWDPWS (2001). Hume Dam Embankment No. 1A, Southern Junction, Dams and Civil Section, New South Wales Department of Public Works & Services, Report No. DC00129.
- Perkins, W. A. (1932). Memorandum to Mr. Hawley, Crane Valley Dam #95-3, Inspected March 14, 1932, California Division of Water Resources.
- PG&E (2005). Annual Surveillance Data, Madera County, Report to the California Department of Water Resources, Division of Safety of Dams. Pacific Gas and Electric Company.
- Pujol-Rius, A., P. Griffin, J. Neal, and O. Taki (1989). Foundation Stabilization of Jackson Lake Dam. Proceedings: *International Conference on Soil Mechanics and Foundation Engineering*. Vol 2.A, 1403-1406.

- Ressi di Cervia, A. L. (1992). History of Slurry Wall Construction. *Special Technical Publication. No. 1129*, ASTM, 3-15.
- Rocscience (2007). Phase2 Version 6.020. Rocscience Inc., Toronto, Ontario, Canada.
- Ryan, C. R. and S. R. Day (2002). Soil-Cement-Bentonite Slurry Walls. *Geotechnical Special Publication No. 1161*, ASCE, 713-727.
- Ryan, C. R. and B. H. Jasperse (1989). Deep Soil Mixing at the Jackson Lake Dam. Proceedings: *Conference on Foundation Engineering, Current Principals and Practice*, ASCE, 254-367.
- Schmertmann, J. H. (2000). The Non-Filter Factor of Safety against Piping Through Sands. *Special Publication No. 111, Judgement and Innovation*, ASCE.
- Sellmeijer, J. B. and M. A. Koenders (1991). A Mathematical Model for Piping. *Applied Mathematical Modeling*, Vol. 115, 645-661.
- Shadix, S. (1981). Seepage at Twin Buttes Dam, San Angelo, Texas. *Bulletin Association of Engineering Geologists* 24: 52-53.
- Shannon & Wilson (2000a). Final Geotechnical Report, Lewiston Levee Seepage Analysis, Lewiston, Idaho, Shannon & Wilson, Inc., Geotechnical and Environmental Consultants.
- Shannon & Wilson (2000b). Final Design Documentation Report, West Lewiston Levee Seepage Repair, Lewiston, Idaho, Shannon & Wilson, Inc., Geotechnical and Environmental Consultants.
- Sherard, J. L. (1986). Hydraulic Fracturing in Embankment Dams. *Journal of Geotechnical Engineering Division*, ASCE, 112(GT10), 905-927.
- Simmons, M. D. (1982). Remedial Treatment Exploration, Wolf Creek Dam, Ky. *Journal of the Geotechnical Engineering Division*, ASCE, 108(GT7), 966-981.
- SJDPRNS (2005). Cherry Flat Dam and Reservoir, No. 24, Santa Clara County, Annual Report to the California Department of Water Resources, Division of Safety of Dams, City of San Jose, Department of Parks, Recreation, and Neighborhood Services.
- Tamaro, G. J. and R. J. Poletto (1992). Slurry Walls-Construction Quality Control. *Special Technical Publication. No. 1129*, ASTM, 26-41.
- Telling, R. M., B. K. Menzies, and J. M. Coulthard (1978a). Design Method for Assessing the Effectiveness of Partially Penetrating Cut-Off Walls. *Ground Engineering*, 11, 48-51.
- Telling, R. M., B. K. Menzies, and N. E. Simons (1978b). Effectiveness of Jointed Cut-Off Walls beneath Dams on Pervious Soil Foundations. *Ground Engineering*, 11, 37.

- Telling, R. M., B. K. Menzies, and N. E. Simons (1978c). Cut-Off Efficiency, Performance and Design. *Ground Engineering*, 11(1): 30-31.
- Tomlinson, S. S. and Y. P. Vaid (2000). Seepage Forces and Confining Pressure Effects on Piping Erosion. *Canadian Geotechnical Journal*, Vol. 37, 1-13.
- URS (2001). Goulburn-Murray Water, Dam Improvement Project, Dam Risk Assessment: Waranga. Prepared for Headworks, Goulburn-Murray Water, URS Australia Pty Ltd.
- URS (2002). Fontonelle Dam Piezometers. Letter Report to U.S. Bureau of Reclamation, URS Australia Pty Ltd.
- USACE (1959). Review of Soils Design Construction and Performance Observations, Wister Dam, Oklahoma, Technical Report No. 3-508, United States Army Waterways Experimentation Station, Vicksburg, Mississippi.
- USACE (1972). Walter F. George Project, Foundation Remedial Work, 1961 - 1972, United States Army Corps of Engineers, Mobile District.
- USACE (1973). Plan and Details of Wolf Creek Dam, Cumberland River, KY., United States Army Corps of Engineers, Nashville District.
- USACE (1974). Report and Evaluation of Safety, Earth Embankment, Wolf Creek Dam, Cumberland River, Kentucky, United States Army Corps of Engineers, Nashville District.
- USACE (1978). Plan of Study, Mill Creek Dam and Reservoir, United States Army Corps of Engineers, Walla Walla District.
- USACE (1979). Mill Creek Flood Control Project, Project Plans, Storage Dam Rehabilitation. United States Army Corps of Engineers, Walla Walla District.
- USACE (1980). Mill Creek Lake, Design Memorandum No. 6, Storage Dam Rehabilitation, United States Army Corps of Engineers, Walla Walla District.
- USACE (1981a). Rehabilitation of Clemson Lower Diversion Dam, Design Memorandum 32, Hartwell Lake Project, Savannah River, Georgia and South Carolina, United States Army Corps of Engineers.
- USACE (1981b). Construction Report, Construction of Concrete Diaphragm Cutoff Wall (Phase 1), Walter F. George Lock and Dam, Contract No. DACW01-81-C-0152, United States Army Corps of Engineers, Mobile District.

USACE (1983). Design Memorandum 33, Rehabilitation of Clemson Upper Diversion Dam, Hartwell Lake, Savannah River, Georgia and South Carolina, United States Army Corps of Engineers, Savannah District.

USACE (1986a). Major Rehabilitation Program Reconnaissance Report, Wister Lake, Poteau River, Oklahoma, United States Army Corps of Engineers, Tulsa District.

USACE (1986b). Engineering Manual EM1110-1901, Seepage Analysis and Control for Dams, United States Army Corps of Engineers.

USACE (1987a). Construction Foundation Report, Hartwell Lake Project, Savannah River, Georgia and South Carolina, Rehabilitation of Clemson Lower Diversion Dam, Contract No. DACW21-82-C-0020, United States Army Corps of Engineers.

USACE (1987b). Mill Creek Lake, Washington, Reconnaissance Report, Storage Dam Seepage Control, United States Army Corps of Engineers.

USACE (1988). Wister Lake, Poteau River, Oklahoma, Design Memorandum No. 1, - Embankment Rehabilitation, United States Army Corps of Engineers, Tulsa District.

USACE (1988b). Wister Lake Embankment Rehabilitation Project Drawings, United States Army Corps of Engineers, Tulsa District. CB060-DMI-0/i.

USACE (1989a). Rehabilitation of Clemson Upper Diversion Dam, Contract No. DACW21-83-C-0066, Construction Foundation Report, United States Army Corps of Engineers, Savannah District.

USACE (1989b). Mill Creek Lake, Design Memorandum No. 5, General Design Memorandum, Project Rehabilitation, United States Army Corps of Engineers, Walla Walla District.

USACE (1991). Construction Foundation Report, Seepage Control Wall, Mud Mountain Dam, Contract No. DACW67-83-C-0047, United States Army Corps of Engineers, Seattle District.

USACE (1995). Beaver Dam Secant Pile Wall Completion Report, United States Army Corps of Engineers.

USACE (1996). Beaver Dam, Periodic Inspection Report, United States Army Corps of Engineers.

USACE (2001). Beaver Dam, Periodic Inspection Report, United States Army Corps of Engineers.

USACE (2002a). Wister Lake, Poteau River, Oklahoma, Periodic Inspection No. 9, Embankment, Outlet Works, and Spillway, United States Army Corps of Engineers, Tulsa District.

USACE (2002b). Mill Creek Project, Storage Dam, Right Abutment Grouting and Seepage Evaluation, United States Army Corps of Engineers.

USACE (2003). Periodic Inspection No. 12, Inspected July 24, 2001, Mud Mountain Dam, White River, Washington, United States Army Corps of Engineers, Seattle District.

USACE (2005). Wolf Creek Dam, Jamestown, Kentucky, Seepage Control, Major Rehabilitation Evaluation Final Report, United States Army Corps of Engineers, Nashville District.

USBOR (1963). Final Construction Report, Navajo Dam, Colorado River Storage Project, United States Department of the Interior, Bureau of Reclamation.

USBOR (1981a). General Design of Seepage Cutoff, Calamus Dam, Pick-Sloan Missouri Basin Program, United States Department of the Interior, Bureau of Reclamation.

USBOR (1981b). Backfill and Connection Design for Slurry Trench Cutoff Wall, Calamus Dam, Pick-Sloan Missouri River Basin, United States Department of the Interior, Bureau of Reclamation.

USBOR (1983). Seepage Analysis Report, Stage 3 Specifications, Calamus Dam, Technical Memorandum No. V-222-B-1-g, United States Department of the Interior, Bureau of Reclamation.

USBOR (1986). Seepage Analysis for Navajo Dam, Right Abutment Foundation Drainage, Technical Memorandum No. NV 230, United States Department of the Interior, Bureau of Reclamation.

USBOR (1992). Meeks Cabin Dam Modification Report, United States Department of the Interior, Bureau of Reclamation.

USBOR (1994). Fontenelle Dam, Post Modification Structural Behavior Report, Seedskaadee Project, United States Department of the Interior, Bureau of Reclamation.

USBOR (1995). Calamus Dam, Geologic Summary Report, United States Department of the Interior, Bureau of Reclamation.

USBOR (1997). Performance Parameters for Navajo Dam, Technical Memorandum NZ-8312-1, United States Department of the Interior, Bureau of Reclamation.

USBOR (1998). Report of Findings, Comprehensive Facility Review, Navajo Dam, United States Department of the Interior, Bureau of Reclamation.

USBOR (1999). Technical Memorandum VM-8313-1, Performance Parameters for Virginia Smith Dam, United States Department of the Interior, Bureau of Reclamation.

- USBOR (2000a). Comprehensive Facility Review for New Waddell Dam, Central Arizona Project, Lower Colorado Region, United States Department of the Interior, Bureau of Reclamation.
- USBOR (2000b). Comprehensive Facility Review, Report of Findings, Twin Buttes Dam, San Angelo, Texas, United States Department of the Interior, Bureau of Reclamation.
- USBOR (2002a). Fontenelle Dam, Comprehensive Facility Review, Seedskafee Project, Wyoming, Upper Colorado Region, United States Department of the Interior, Bureau of Reclamation.
- USBOR (2002b). Periodic Facility Review, New Waddell Dam, Central Arizona Project, Lower Colorado Region, United States Department of the Interior, Bureau of Reclamation.
- USBOR (2003a). Virginia Smith Dam, Comprehensive Facility Review, North Loup Project, PSMRBP, Nebraska, United States Department of the Interior, Bureau of Reclamation.
- USBOR (2003b). Meeks Cabin Dam, Comprehensive Facility Review, Lyman Project, Wyoming, United States Department of the Interior, Bureau of Reclamation.
- USBOR (2004). Navajo Dam, Comprehensive Facility Review, Colorado River Storage Project, New Mexico, Upper Colorado Region, United States Department of the Interior, Bureau of Reclamation.
- USBOR (2005). Jackson Lake Dam, Comprehensive Facility Review, Minidoka Project, Pacific Northwest Region, United States Department of the Interior, Bureau of Reclamation.
- Vanberg, B. (1980). Inspection of Dam Report, Lake Valley Dam No. 97-32, Dates of Inspection: September 11 and 23 and October 1, 1980, California Department of Water Resources, Division of Dam Safety.
- Vanel, P. (1992). Making Diaphragm Wall Joints Watertight with the CWS System. *Special Technical Publication. No. 1129*, ASTM, 16-25.
- Von Thun, J. L. (1990). The Quail Creek Dike Failure. *Dam Foundation Engineering, Tenth Annual USCOLD Lecture, New Orleans, Louisiana*, United States Committee on Large Dams.
- Wan, C. F. and R. Fell (2002). Investigation of Internal Erosion and Piping of Soils in Embankment Dams by the Slot Erosion Test and Hole Erosion Test, UNICIV Report No. R-412, University of New South Wales.
- Wan, C. F. and R. Fell (2004a). Investigation of Rate of Erosion of Soils in Embankment Dams. *Journal of Geotechnical and Geoenvironmental Engineering*, ASCE, 130(4), 373-380.

Wan, C. F. and R. Fell (2004b). Laboratory Tests on the Rate of Piping Erosion of Soils in Embankment Dams. *Geotechnical Testing Journal*, ASCE, 27(3), 295-303.

Woodward-Clyde-Consultants (1984). Geotechnical Engineering Services, Manasquan Reservoir Dam, Prepared for New Jersey Water Supply Authority, Clinton New Jersey.

Woodward-Clyde-Consultants (1988). Phase I and II Engineering Services, Chambers Lake Dam, Near Cameron Pass, Colorado, Prepared for Water Supply and Storage Company, Fort Collins, Colorado.

Woodward-Clyde-Consultants (1990). Instrumentation Summary Report, Manasquan Reservoir Dam, Prepared for New Jersey Water Supply Authority, Clinton New Jersey.

Woodward-Clyde-Consultants (1992). Record Drawings, Chambers Lake Dam Rehabilitation, Prepared for Water Supply and Storage Company, Fort Collins, Colorado.

Xanthakos, P. P. (1979). *Slurry Walls*, McGraw Hill.

Zoccola, M. F., Haskins, Tommy A., Jackson, Daphne M. (2006). The Problem is the Solution: A History of Seepage, Piping, and Remediation in a Karst Foundation at Wolf Creek Dam. Proceedings: *26th USSD Conference – The Roll of Dams in the 21st Century*, San Antonio, TX, United States Society on Dams, 141-150.