

List of Figures

Figure 1.1. Timber framing for a great room near Blacksburg, VA.....	2
Figure 1.2. Contemporary timber frame interior with SIP walls and roof.....	3
Figure 1.3. Typical elements of a mortise and tenon joint.....	4
Figure 1.4. Typical post-frame building.....	6
Figure 2.1. Eave deflections at 425 lb (1.89 kN) load for all test configurations	22
Figure 3.1. Example of a basic test panel	32
Figure 3.2. Interface between timber, OSB spacer strips and SIPs.....	33
Figure 3.3. Edge board installation around perimeter of SIPs	35
Figure 3.4. 8 ft x 24 ft (2.44 m x 7.32 m) basic test panel assembly.....	39
Figure 3.5. 20 ft x 24 ft (6.10 m x 7.32 m) full-scale test panel assembly.....	40
Figure 3.6. End rafter to ridge purlin joint.....	41
Figure 3.7. Center rafter to ridge purlin joint.....	42
Figure 3.8. End rafter to purlin joint	43
Figure 3.9. Center rafter to purlin joint	44
Figure 3.10. End rafter, post stub and plate joint.....	45
Figure 3.11. Center rafter, post stub and plate joint.....	46
Figure 3.12. Loading and support conditions	48
Figure 3.13. Displacement measurement locations	49
Figure 3.14. Pin utilized for diagonal measurements.....	51
Figure 3.15. Data collection sheet.....	55
Figure 3.16. Outer rafter end support.....	59
Figure 3.17. Center rafter roller restraint.....	61
Figure 4.1. Assembly 1 load-deflection plot	72
Figure 4.2. Assembly 1 screw conditions	74
Figure 4.3. Separation of SIPs and broken strap after Assembly 1 failure	75
Figure 4.4. Assembly 2 load-deflection plot	77
Figure 4.5. Assembly 3 load-deflection plot	79
Figure 4.6. Assembly 3 fractured post stub	80

Figure 4.7. Steel channel reinforcement	82
Figure 4.8. Assembly 4 load-deflection plot	83
Figure 4.9. Assembly 4 eave plate damage	85
Figure 4.10. Assembly 4 fractured post stub	86
Figure 4.11. Assembly 4 bent screw sample	87
Figure 4.12. Assembly 4 broken strap	88
Figure 4.13. Assembly 4 damaged pegs.....	89
Figure 4.14. Assembly 4 spline joint pegs after failure.....	90
Figure 4.15. Assembly 5 load-deflection plot	91
Figure 4.16. Assembly 5 bent screw samples.....	93
Figure 4.17. Assembly 5 global buckling.....	94
Figure 4.18. Assembly 5 separation of SIP skins and edge boards	95
Figure 4.19. Assembly 5 spline joint pegs after failure.....	96
Figure 4.20. 8 ft x 24 ft (2.44 m x 7.32 m) assembly load-deflection comparisons	100
Figure 4.21. 20 ft x 24 ft (6.10 m x 7.32 m) assembly load-deflection comparisons	101
Figure 4.22. Assembly load-deflection comparisons for all tests	102
Figure 4.23. Assembly 2 example hysteresis plot.....	106
Figure 4.24. Typical hysteresis loop plot.....	107
Figure 4.25. Assembly 2 cyclic stiffness plot	109
Figure 4.26. Assembly 2 strain energy plot.....	110
Figure 4.27. Assembly 2 hysteretic energy plot	111
Figure 4.28. Assembly 2 equivalent viscous damping plot	112
Figure 4.29. Shear stiffness versus diaphragm length example	116
Figure 5.1. Wind loads and structural analog of center timber frame	129
Figure 5.2. Combined stress index versus aspect ratio for highly stressed members	136
Figure 5.3. Maximum roof shear versus aspect ratio	137
Figure 5.4. Combined stress index versus aspect ratio for Member 27	138
Figure 5.5. Seismic loads and structural analog of center timber frame.....	143
Figure 6.1. Timber frame structural analog with roller reaction at eave.....	148
Figure A.1. Stiffness loading sequence with 0.10 in. (2.5 mm) maximum displacement.....	167

Figure A.2. Stiffness loading sequence with 0.25 in. (6.4 mm) maximum displacement.....	169
Figure A.3. Failure loading sequence with 1.02 in. (26 mm) reference displacement	171
Figure B.1. Bent and broken screw examples.....	174
Figure B.2. Assembly 1 SIP screw locations and conditions	175
Figure B.3. Assembly 2 SIP screw locations and conditions	176
Figure B.4. Assembly 3 SIP screw locations and conditions	177
Figure B.5. Assembly 4 SIP screw locations and conditions	178
Figure B.6. Assembly 5 SIP screw locations and conditions	179
Figure C.1. Assembly 1 cyclic stiffness comparisons	181
Figure C.2. Assembly 1 strain energy comparisons.....	182
Figure C.3. Assembly 1 hysteretic energy comparisons	183
Figure C.4. Assembly 1 equivalent viscous damping comparisons	184
Figure C.5. Assembly 2 cyclic stiffness comparisons	186
Figure C.6. Assembly 2 strain energy comparisons.....	187
Figure C.7. Assembly 2 hysteretic energy comparisons	188
Figure C.8. Assembly 2 equivalent viscous damping comparisons	189
Figure C.9. Assembly 3 cyclic stiffness comparisons	191
Figure C.10. Assembly 3 strain energy comparisons.....	192
Figure C.11. Assembly 3 hysteretic energy comparisons.....	193
Figure C.12. Assembly 3 equivalent viscous damping comparisons	194
Figure C.13. Assembly 4 cyclic stiffness comparisons	196
Figure C.14. Assembly 4 strain energy comparisons.....	197
Figure C.15. Assembly 4 hysteretic energy comparisons.....	198
Figure C.16. Assembly 4 equivalent viscous damping comparisons	199
Figure C.17. Assembly 5 cyclic stiffness comparisons	201
Figure C.18. Assembly 5 strain energy comparisons.....	202
Figure C.19. Assembly 5 hysteretic energy comparisons.....	203
Figure C.20. Assembly 5 equivalent viscous damping comparisons	204