

---

**Appendix B**  
**References for EPOLLS Case Studies**

---

**B.1. 1906 San Francisco, California, Earthquake . . . . . Slide Nos. 1 - 4.**

Bennett, M. J., and Tinsley, J. C. III (1995). "Geotechnical data from surface and subsurface samples outside of and within liquefaction-related ground failures caused by the October 17, 1989, Loma Prieta earthquake, Santa Cruz and Monterey Counties, California." *Open-File Report 95-663*, U.S. Geological Survey, Menlo Park, Calif.

Harding Lawson Associates, Dames & Moore, Kennedy/Jenks/Chilton, and EQE Engineering (1991). "Final report: Liquefaction study, Marina District and Sullivan Marsh Area, San Francisco, California." Report prepared for City and County of San Francisco, Dept. of Public Works, HLA Job No. 17952,041.04, August 20.

Harding Lawson Associates, Dames & Moore, Kennedy/Jenks/Chilton, and EQE Engineering (1992). "Final report: Liquefaction study, North Beach, Embarcadero Waterfront, South Beach, and Upper Mission Creek Area, San Francisco, California." Report prepared for City and County of San Francisco, Dept. of Public Works, HLA Job No. 17952,041.04, January 10.

O'Rourke, T. D., Beaujon, P. A., and Scawthorn, C.R. (1992). "Large ground deformations and their effects on lifeline facilities: 1906 San Francisco earthquake." *Case Studies of Liquefaction and Lifeline Performance During Past Earthquakes, Volume 2: United States Case Studies, Tech. Rep. NCEER-92-0002*, T. D. O'Rourke and M. Hamada (eds.), February 17, 130 pages.

O'Rourke, T. D., and Lane, P. A. (1989). "Liquefaction hazards and their effects on buried pipelines." *Tech. Rep NCEER-89-0007*, National Center for Earthquake Engineering Research, Buffalo, NY, February 1.

Youd, T. L., and Bennett, M. J. (1981). "Liquefaction site studies following 1979 Imperial Valley earthquake." *In situ Testing to Evaluate Liquefaction Susceptibility, Preprint 81-544*, ASCE National Convention, St. Louis, Missouri, October 27.

Youd, T. L., and Hoose, S. N. (1976). "Liquefaction during 1906 San Francisco earthquake." *J. Geotech. Engrg. Div.*, ASCE, Vol. 102, No. GT5, May, pp. 425-439.

Youd, T. L., and Hoose, S. N. (1978). "Historic ground failures in northern California triggered by earthquakes." *U.S. Geological Survey Professional Paper 993*, 177 pages.

### **B.2. 1923 Kanto, Japan, Earthquake . . . . . Slide No. 5.**

Hamada, M., Wakamatsu, K., Yasuda, S. (1992). "Liquefaction-induced ground deformations during the 1923 Kanto earthquake." *Case Studies of Liquefaction and Lifeline Performance During Past Earthquakes, Volume 1: Japanese Case Studies, Tech. Rep. NCEER-92-0001*, M. Hamada and T. D. O'Rourke (eds.), February 17, 39 pages.

Matsu'ura, M. and Iwasaki, T. (1983). "Study on coseismic and postseismic crustal movements associated with the 1923 Kanto earthquake." *Tectonophysics*, Vol. 97, Elsevier Science Pub., Amsterdam, pp. 201-215.

Wakamatsu, K., Hamada, M., Yasuda, S., and Morimoto, I. (1989). "Liquefaction induced ground displacement during the 1923 Kanto earthquake." *Proc., 2<sup>nd</sup> U.S.-Japan Workshop on Liquefaction, Large Ground Deformation and Their Effects on Lifelines, Tech. Rep. NCEER-89-0032*, T. D. O'Rourke and M. Hamada (eds.), December 1, pp. 36-49.

### **B.3. 1948 Fukui, Japan, Earthquake . . . . . Slide Nos. 6 - 9.**

Doi, M., and Hamada, M. (1992). "A summary of case studies on liquefaction-induced ground displacements." *Proc., 4<sup>th</sup> Japan-U.S. Workshop on Earthquake Resistant Design of Lifeline Facilities and Countermeasures for Soil Liquefaction, Tech. Rep. NCEER-92-0019*, M. Hamada and T. D. O'Rourke (eds.), August 12, pp. 115-129.

Hamada, M., Wakamatsu, K., and Yasuda, S. (1989). "Liquefaction-induced ground displacement during the 1948 Fukui earthquake." *Proc., 2<sup>nd</sup> U.S.-Japan Workshop on Liquefaction, Large Ground Deformation and Their Effects on Lifelines, Tech. Rep. NCEER-89-0032*, T. D. O'Rourke and M. Hamada (eds.), December 1, pp. 6-15.

Hamada, M., Yasuda, S., and Wakamatsu, K. (1992). "Large ground deformations and their effects on lifelines: 1948 Fukui earthquake." *Case Studies of Liquefaction and Lifeline Performance During Past Earthquakes, Volume 1: Japanese Case Studies, Tech. Rep. NCEER-92-0001*, M. Hamada and T. D. O'Rourke (eds.), February 17, 42 pages.

#### **B.4. 1964 Prince William Sound, Alaska, Earthquake . . . . . Slide Nos. 10 - 24.**

Bartlett, S. F., and Youd, T. L. (1992). "Case histories of lateral spreads caused by the 1964 Alaska earthquake." *Case Studies of Liquefaction and Lifeline Performance During Past Earthquakes, Volume 2: United States Case Studies, Tech. Rep. NCEER-92-0002*, T. D. O'Rourke and M. Hamada (eds.), February 17, 127 pages.

Kachadoorian, R. (1968). "Effects of the earthquake of March 27, 1964, on the Alaska highway system." *U.S. Geological Survey Professional Paper 545-C*, 66 pages.

McCulloch, D. S., and Bonilla, M. G. (1970). "Effects of the earthquake of March 27, 1964, on the Alaska Railroad." *U.S. Geological Survey Professional Paper 545-D*, 161 pages.

Ross, G. A., Seed, H. B., and Migliaccio, R. R. (1973). "Performance of highway bridge foundations." *The great Alaska earthquake of 1964, Volume 6: Engineering*, National Academy of Science, Washington, D. C., pp. 190-242.

Youd, T. L., and Bartlett, S. F. (1991). "Case histories of lateral spreads from the 1964 Alaska earthquake." *Proc., 3<sup>rd</sup> Japan-U.S. Workshop on Earthquake Resistant Design of Lifeline Facilities and Countermeasures for Soil Liquefaction, Tech. Rep. NCEER-91-0001*, T. D. O'Rourke and M. Hamada (eds.), February 1, pp. 175-189.

#### **B.5. 1964 Niigata, Japan, Earthquake . . . . . Slide Nos. 25 - 39.**

Doi, M., and Hamada, M. (1992). "A summary of case studies on liquefaction-induced ground displacements." *Proc., 4<sup>th</sup> Japan-U.S. Workshop on Earthquake Resistant Design of Lifeline Facilities and Countermeasures for Soil Liquefaction, Tech. Rep. NCEER-92-0019*, M. Hamada and T. D. O'Rourke (eds.), August 12, pp. 115-129.

Hamada, M. (1992). "Large ground deformations and their effects on lifelines: 1964 Niigata earthquake." *Case Studies of Liquefaction and Lifeline Performance During Past Earthquakes, Volume 1: Japanese Case Studies, Tech. Rep. NCEER-92-0001*, M. Hamada and T. D. O'Rourke (eds.), February 17, 123 pages.

- Hamada, M., Towhata, I., Yasuda, S., Isoyama, R. (1987). "Study of permanent ground displacement induced by seismic liquefaction." *Computers and Geotechnics*, Vol. 4, Elsevier Applied Science Pub., pp. 197-220.
- Hamada, M., Yasuda, S., Isoyama, R., and Emoto, K. (1986). "Study on liquefaction induced permanent ground displacements." Published by the *Association for the Development of Earthquake Prediction in Japan*, November 1, 87 pages.
- Hirono, T. (1968). "Seismometrical features." *General report on the Niigata earthquake of 1964*, H. Kawasumi (ed.), Tokyo Electrical Engineering College Press, March, pp. 47-62.
- Kawasumi, H. (ed.) (1968). *General report on the Niigata earthquake of 1964*, Tokyo Electrical Engineering College Press, March.
- Satake, K. and Abe, K. (1983). "A fault model for the Niigata, Japan, earthquake of June 16, 1964." *J. Physics Earth*, Vol. 31, Center for Academic Publications, Japan, pp. 217-223.
- Seed, H. B. and Idriss, I. M. (1967). "Analysis of soil liquefaction: Niigata earthquake." *J. Soil Mech. Found. Div.*, ASCE, Vol. 93, No. SM3, May, pp. 83-108.
- Yasuda, S., Hamada, M., Wakamatsu, K., and Morimoto, I. (1989). "Liquefaction induced permanent ground displacements in Niigata City." *Proc., 2<sup>nd</sup> U.S.-Japan Workshop on Liquefaction, Large Ground Deformation and Their Effects on Lifelines*, Tech. Rep. NCEER-89-0032, T. D. O'Rourke and M. Hamada (eds.), December 1, pp. 67-81.
- Youd, T. L., and Kiehl, S. J. (1996). "Distribution of ground displacements and strains induced by lateral spread during the 1964 Niigata earthquake." *Proc., 6<sup>th</sup> Japan-U.S. Workshop on Earthquake Resistant Design of Lifeline Facilities and Countermeasures Against Soil Liquefaction*, Tech. Rep. NCEER-96-0012, M. Hamada and T. D. O'Rourke (eds.), September 11, pp. 205-219.

**B.6. 1971 San Fernando, California, Earthquake . . . . . Slide Nos. 40 - 41.**

- Barrows, A. G., Kahle, J. E., Weber, F. H. Jr., and Saul, R. B. (1973). "Map of surface breaks resulting from the San Fernando, California, earthquake of February 9, 1971." *San Fernando, California, Earthquake of February 9, 1971*, Vol. 3, National Oceanic and Atmospheric Admin., Washington, D. C., pp. 127-135.

- Bennett, M. J. (1989). "Liquefaction analysis of the 1971 ground failure at the San Fernando Valley Juvenile Hall, California." *Bulletin of the Assoc. of Engrg. Geologists*, Vol. 26, No. 2, pp. 209-226.
- Fallgren, R. B., and Smith, J. L. (1973). "Ground displacement at San Fernando Valley Juvenile Hall during San Fernando earthquake." *San Fernando, California, Earthquake of February 9, 1971*, Vol. 3, National Oceanic and Atmospheric Admin., Washington, D. C., 1973, pp. 189-196.
- Housner, G. W. (1971). "General features of the San Fernando earthquake." *Engineering features of the San Fernando earthquake of February 9, 1971, Report No. EERL 71-02*, P. C. Jennings (ed.), California Institute of Technology, Pasadena, June.
- Maley, R. P., and Cloud, W. K. (1973). "Strong-motion accelerograph records." *San Fernando, California, Earthquake of February 9, 1971*, Vol. 3, National Oceanic and Atmospheric Admin., Washington, D. C., 1973, pp. 325-348.
- Marachi, N. D. (1973). "Dynamic soil problems at the Joseph Jensen Filtration Plant." *San Fernando, California, Earthquake of February 9, 1971*, Vol. 1, National Oceanic and Atmospheric Admin., Washington, D. C., pp. 815-820.
- O'Rourke, T. D., Roth, B. L., and Hamada, M. (1992). "Large ground deformations and their effects on lifeline facilities: 1971 San Fernando earthquake." *Case Studies of Liquefaction and Lifeline Performance During Past Earthquakes, Volume 2: United States Case Studies, Tech. Rep. NCEER-92-0002*, T. D. O'Rourke and M. Hamada (eds.), February 17, 85 pages.
- O'Rourke, T.D., Roth, B. L., and Hamada, M. (1989). "A case study of large ground deformation during the 1971 San Fernando earthquake." *Proc., 2<sup>nd</sup> U.S.-Japan Workshop on Liquefaction, Large Ground Deformation and Their Effects on Lifelines, Tech. Rep. NCEER-89-0032*, T. D. O'Rourke and M. Hamada (eds.), December 1, pp. 50-66.
- Youd, T. L. (1973). "Ground movements in Van Norman Lake vicinity during San Fernando earthquake." *San Fernando, California, Earthquake of February 9, 1971*, Vol. 3, National Oceanic and Atmospheric Admin., Washington, D. C., pp. 197-206.
- Youd, T. L. (1971). "Landsliding in the vicinity of the Van Norman Lakes." *The San Fernando, California, Earthquake of February 9, 1971, US Geological Survey Professional Paper 733*, pp. 105-109.

**B.7. 1976 Guatemala Earthquake . . . . . Slide No. 42.**

Dewey, J. W., and Julian, B. R. (1976). "Main event source parameters from teleseismic data." *The Guatemala Earthquake of February 4, 1976, A Preliminary Report, U.S. Geological Survey Professional Paper 1002*, A. F. Espinoza (ed.), pp. 19-23.

Hoose, S. N., Wilson, R. C., and Rosenfeld, J. H. (1978). "Liquefaction-caused ground failure during the February 4, 1976, Guatemala earthquake." *Proc. Int. Symposium on the February 4<sup>th</sup>, 1976, Guatemalan Earthquake and the Reconstruction Process*, Vol. 1, 31 pages.

Person, W., Spence, W., and Dewey, J. W. (1976). "Main event and principal aftershocks from teleseismic data." *The Guatemala Earthquake of February 4, 1976, A Preliminary Report, U.S. Geological Survey Professional Paper 1002*, A. F. Espinoza (ed.), pp. 17-18.

Seed, H. B., Arango, I., Chan, C. K., Gomez-Masso, A., Ascoli, R. G. (1981). "Earthquake-induced liquefaction near Lake Amatitlan, Guatemala." *J. of Geotech. Engrg. Div., ASCE*, Vol 107, No. GT4, April, pp 501-518.

**B.8. 1979 Imperial Valley, California, Earthquake . . . . . Slide Nos. 43 - 44.**

Chavez, D., Gonzales, J., Reyes, A., Medina, M., Duarte, C., Brune, J. N., Vernon, F. L. III, Simons, R., Hutton, L. K., German, P. T., and Johnson, C. E. (1982). "Main-shock location and magnitude determination using combined U.S. and Mexican data." *The Imperial Valley, California, Earthquake of October 15, 1979, U.S. Geological Survey Professional Paper 1254*, pp. 51-54.

Dobry, R., Baziar, M. H., O'Rourke, T. D., Roth, B. L., and Youd, T. L. (1992). "Liquefaction and ground failure in the Imperial Valley, southern California, during the 1979, 1981, and 1987 earthquakes." *Case Studies of Liquefaction and Lifeline Performance During Past Earthquakes, Volume 2: United States Case Studies, Tech. Rep. NCEER-92-0002*, T. D. O'Rourke and M. Hamada (eds.), February 17, 85 pages.

Porcella, R. L., Matthiesen, R. B., and Maley, R. P. (1982). "Strong-motion data recorded in the United States." *The Imperial Valley, California, Earthquake of October 15, 1979, U.S. Geological Survey Professional Paper 1254*, pp. 289-318.

Youd, T. L., and Bennett, M. J. (1983). "Liquefaction sites, Imperial Valley, California." *J. Geotech. Engrg., ASCE*, Vol. 109, No. 3, March, pp. 440-457.

Youd, T. L., and Bennett, M. J. (1981). "Liquefaction site studies following 1979 Imperial Valley earthquake." *In situ Testing to Evaluate Liquefaction Susceptibility, Preprint 81-544*, ASCE National Convention, St. Louis, Missouri, October 27.

Youd, T. L., and Wieczorek, G. F. (1982). "Liquefaction and secondary ground failure." *The Imperial Valley, California, Earthquake of October 15, 1979, U.S. Geological Survey Professional Paper 1254*, pp. 223-246.

**B.9. 1983 Nihonkai-Chubu, Japan, Earthquake . . . . . Slide Nos. 45 - 49.**

Hamada, M. (1992). "Large ground deformations and their effects on lifelines: 1983 Nihonkai-Chubu earthquake." *Case Studies of Liquefaction and Lifeline Performance During Past Earthquakes, Volume 1: Japanese Case Studies, Tech. Rep. NCEER-92-0001*, M. Hamada and T. D. O'Rourke (eds.), February 17, 85 pages.

Hamada, M., Kubo, K., and Saito, K. (1985). "Large ground displacement and buried pipe failure by soil liquefaction during 1983 Nihonkai-Chubu earthquake." *Seismic Performance of Pipelines and Storage Tanks, Proc. of 1985 Pressure Vessels and Piping Conference*, ASME, PVP-Vol. 98-4, June, pp. 11-18.

Hamada, M., Yasuda, S., Isoyama, R., and Emoto, K. (1986). "Study on liquefaction induced permanent ground displacements." Published by the *Association for the Development of Earthquake Prediction in Japan*, 87 pages.

Satake, K. (1985). "The mechanism of the 1983 Japan Sea earthquake as inferred from long-period surface waves and tsunamis." *Physics of the Earth and Planetary Interiors*, Vol. 37, Elsevier Science Pub., Amsterdam, pp. 249-260.

**B.10. 1983 Borah Peak, Idaho, Earthquake . . . . . Slide Nos. 50 - 51.**

Andrus, R. D., Stokoe, K. H., and Roësset, J. M. (1991). "Liquefaction of gravelly soil at Pence Ranch during the 1983 Borah Peak, Idaho earthquake." *Proc. of the Fifth International Conference on Soil Dynamics and Earthquake Engineering*, Karlsruhe, Germany, Sept. 1991.

Andrus, R. D., and Youd, T. L. (1987). "Subsurface investigation of liquefaction-induced lateral spread Thousand Springs Valley, Idaho." *U.S. Army Corps of Engineers, Misc. Paper GL-87-8*, 106 pages.

- Harder, L. F. Jr. (1988). "Use of penetration tests to determine the cyclic loading resistance of gravelly soils during earthquake shaking." A dissertation submitted to the Civil Engrg. Dept., University of California, Berkeley, in partial satisfaction of the requirements for the degree Doctor of Philosophy.
- Harder, L. F. Jr. (1994). "Becker test results from gravel liquefaction sites." *Ground Failures Under Seismic Conditions, ASCE Geotech. Special Pub. No. 44*, S. Prakash and P. Dakoulas (eds.), October, pp. 201-220.
- Jackson, S. M. and Boatwright, J. (1985). "The Borah Peak, Idaho earthquake of October 28, 1983 - Strong ground motion." *Earthquake Spectra*, Earthquake Engineering Research Institute, Vol. 2, No. 1, pp. 51-69.
- Jones, N. L., and Wright, S. G. (1993). "Subsurface characterization with solid models." *J. of Geotech. Engrg.*, ASCE, Vol. 119, No. 11, November, pp. 1823-1839.
- Taylor, C. L., Cline, K. M., Page, W. D., and Schwartz, D. P. (1985). "The Borah Peak, Idaho earthquake of October 28, 1983 - Surface faulting and other phenomena." *Earthquake Spectra*, Earthquake Engineering Research Institute, Vol. 2, No. 1, pp. 23-49.
- Youd, T. L., Harp, E. L., Keefer, D. K., and Wilson, R. C. (1985). "The Borah Peak earthquake of 1983 - liquefaction". *Earthquake Spectra*, Earthquake Engineering Research Institute, Vol. 2, No. 1, pp. 71-89.

**B.11. 1987 Superstition Hills, California, Earthquake . . . . . Slide No. 52.**

- Bennett, M. J. McLaughlin, P. V., Sarimento, J. S., and Youd, T. L. (1984). "Geotechnical investigation of liquefaction sites, Imperial Valley, California." *Open-File Report 84-252*, U.S. Geological Survey, Menlo Park, California, 103 pages.
- Dobry, R., Baziar, M. H., O'Rourke, T. D., Roth, B. L., and Youd, T. L. (1992). "Liquefaction and ground failure in the Imperial Valley, southern California, during the 1979, 1981, and 1987 earthquakes." *Case Studies of Liquefaction and Lifeline Performance During Past Earthquakes, Volume 2: United States Case Studies, Tech. Rep. NCEER-92-0002*, T. D. O'Rourke and M. Hamada (eds.), February 17, 85 pages.
- Gu, W. H., Morgenstern, N. R., and Robertson, P. K. (1994). "Postearthquake deformation analysis of Wildlife site." *J. Geotech. Engrg.*, ASCE, Vol. 120, No. 2, February, pp. 274-289.



Holzer, T. L., Bennett, M. J., and Youd, T. L. (1989). "Lateral spreading field experiments by the U.S. Geological Survey." *Proc., 2<sup>nd</sup> U.S.-Japan Workshop on Liquefaction, Large Ground Deformation and Their Effects on Lifelines, Tech. Rep. NCEER-89-0032*, T. D. O'Rourke and M. Hamada (eds.), December 1, pp. 82-101.

Holzer, T. L., Youd, T. L., and Bennett, M. J. (1988) "In situ measurement of pore-pressure build-up during liquefaction." *20th Joint UJNR Panel on Wind and Seismic Effects*, pp. 118-130.

Holzer, T. L., Youd, T. L., and Hanks, T. C. (1989) "Dynamics of liquefaction during the 1987 Superstition Hills, California, earthquake." *Science*, Vol 244, pp. 56-59.

**B.12. 1989 Loma Prieta, California, Earthquake . . . . . Slide Nos. 53 - 57.**

Barminski, R. F., Jr. (1993). "Onshore and offshore effects of the 1989 Loma Prieta earthquake in the Moss Landing, California, area." A thesis presented to the faculty of Moss Landing Marine Laboratories, San Jose State University, in partial fulfillment of the requirements for the degree Master of Science, December, 48 pages.

Bennett, M. J., and Tinsley, J. C. III (1995). "Geotechnical data from surface and subsurface samples outside of and within liquefaction-related ground failures caused by the October 17, 1989, Loma Prieta earthquake, Santa Cruz and Monterey Counties, California." *Open-File Report 95-663*, U.S. Geological Survey, Menlo Park, Calif.

Clough, G. W., Martin, J. R., II, and Chameau, J. L. (1994). "The geotechnical aspects." *Practical Lessons from the Loma Prieta Earthquake*, National Research Council, National Academy Press, Washington, D.C., pp. 29-63.

Darragh, R. D., Taylor, H. T., Scawthorn, C., Seidel, D., and Ng, C. (1992). "Liquefaction study, Sullivan Marsh and Mission Creek, San Francisco, California." *Proc., 4<sup>th</sup> Japan-U.S. Workshop on Earthquake Resistant Design of Lifeline Facilities and Countermeasures for Soil Liquefaction, Tech. Rep. NCEER-92-0019*, M. Hamada and T. D. O'Rourke (eds.), August 12, pp. 205-221.

Earthquake Engineering Research Institute (1990). "Loma Prieta earthquake reconnaissance report: Chapter 4, Geotechnical Aspects." *Earthquake Spectra*, suppl. to Vol. 6, L. Benuska (ed.), May, pp. 81-125.

- Governor's Board of Inquiry on the 1989 Loma Prieta Earthquake (1990). *Competing against time*. Report to Governor George Deukmejian, G. W. Housner (chairman), May 31, 264 pages.
- Greene, H. G., Gardner-Taggart, J., Ledbetter, M. T., Barminski, R., Chase, T. E., Hicks, K. R., and Baxter, C. (1991). "Offshore and onshore liquefaction at Moss Landing spit, central California - Result of the October 17, 1989, Loma Prieta earthquake." *Geology*, Vol. 19, September, pp. 945-949.
- Hanks, T. C., and Krawinkler, H. (1991). "The 1989 Loma Prieta earthquake and its effects: Introduction to the special issue." *Bul. Seismological Society of America*, Vol. 81, No. 5, October, pp. 1415-1423.
- Harding Lawson Associates, Dames & Moore, Kennedy/Jenks/Chilton, and EQE Engineering (1991). "Final report: Liquefaction study, Marina District and Sullivan Marsh Area, San Francisco, California." Report prepared for City and County of San Francisco, Dept. of Public Works, HLA Job No. 17952,041.04, August 20.
- Harding Lawson Associates, Dames & Moore, Kennedy/Jenks/Chilton, and EQE Engineering (1992). "Final report: Liquefaction study, North Beach, Embarcadero Waterfront, South Beach, and Upper Mission Creek Area, San Francisco, California." Report prepared for City and County of San Francisco, Dept. of Public Works, HLA Job No. 17952,041.04, January 10.
- Holzer, T. L., Tinsley, J. C., III, Bennett, M. J., and Mueller, C. S. (1994). Observed and predicted ground deformation - Miller Farm lateral spread, Watsonville, California." *Proc., 5<sup>th</sup> U.S.-Japan Workshop on Earthquake Resistant Design of Lifeline Facilities and Countermeasures for Soil Liquefaction*, Tech. Rep. NCEER-94-0026, T. D. O'Rourke and M. Hamada (eds.), pp. 79-99.
- O'Rourke, T. D., Meyersohn, W. D., Stewart, H. E., Pease, J. W., and Miyajima, M. (1992). "Site response and soil liquefaction in San Francisco during the Loma Prieta earthquake." *Proc., 4<sup>th</sup> Japan-U.S. Workshop on Earthquake Resistant Design of Lifeline Facilities and Countermeasures for Soil Liquefaction*, Tech. Rep. NCEER-92-0019, M. Hamada and T.D. O'Rourke (eds.), August 12, pp. 53-70.
- O'Rourke, T. D., and Pease, J. W. (1992). "Large ground deformations and their effects on lifeline facilities: 1989 Loma Prieta Earthquake." *Case Studies of Liquefaction and Lifeline Performance During Past Earthquakes, Volume 2: United States Case Studies*, Tech. Rep. NCEER-92-0002, T. D. O'Rourke and M. Hamada (eds.), February 17, 85 pages.

Seed, R. B., Dickenson, S. E., Riemer, M. F., Bray, J. D., Sitar, N., Mitchell, J. K., Idriss, I. M., Kayen, R. E., Kropp, A., Harder, L. F. Jr., and Power, M. S. (1990). "Preliminary report on the principal geotechnical aspects of the October 17, 1989 Loma Prieta earthquake." *Report No. UCB/EERC-90/05*, Earthquake Engineering Research Center, University of California, Berkeley, April, 137 pages.

Tinsley, J. C., and Dupré, W. R. (1992). "Liquefaction hazard mapping, depositional faces, and lateral spreading ground failure in the Monterey Bay area, central California, during the 10/17/89 Loma Prieta earthquake." *Proc., 4<sup>th</sup> Japan-U.S. Workshop on Earthquake Resistant Design of Lifeline Facilities and Countermeasures for Soil Liquefaction, Tech. Rep. NCEER-92-0019*, M. Hamada and T. D. O'Rourke (eds.), August 12, pp. 71-85.

Tuttle, M., Cowie, P., Tinsley, J. Benett, M., and Berrill, J. (1990). "Liquefaction and foundation failure of Chevron oil and gasoline tanks at Moss Landing, California." *Geophysical Research Letters*, Vol. 17, No. 10, September, pp. 1797-1800.

### **B.13. 1990 Luzon, Philippines, Earthquake . . . . . Slide Nos. 100 - 103.**

Earthquake Engineering Research Institute (1991). "Philippines earthquake reconnaissance report: Chapter 1, Geoscience and geotechnical." *Earthquake Spectra*, Suppl. A to Vol. 7, A J. Schiff (ed.), October, pp. 1-15.

Ishihara, K., Acacio, A., and Towhata, I. (1993). "Liquefaction-induced ground damage in Dagupan in the July 16, 1990 Luzon earthquake." *Soils and Foundations*, JSSMFE, Vol. 33, No. 1, March, pp. 133-154.

Ishihara, K., Verdugo, R., and Acacio, A. A. (1991). "Characterization of cyclic behavior of sand and post-seismic stability analyses." *Proc., 9<sup>th</sup> Asian Regional Conf. Soil Mech. Found. Engrg.*, Vol. 2, Bangkok, Thailand, December, pp. 45-67.

Tokimatsu, K., Kojima, H., Kuwayama, S., Abe, A., Midorikawa, S. (1994). "Liquefaction-induced damage to buildings in 1990 Luzon earthquake." *J. Geotech. Engrg.*, ASCE, Vol. 120, No. 2, February, pp. 290-307.

Wakamatsu, K., Hamada, M., Tazoh, T., Yoshida, N., and Ando, T. (1991). "Liquefaction-induced ground failure during the 1990 Philippines earthquake." *Proc., 3<sup>rd</sup> Japan-U.S. Workshop on Earthquake Resistant Design of Lifeline Facilities and Countermeasures for Soil Liquefaction, Tech. Rep. NCEER-91-0001*, T. D. O'Rourke and M. Hamada (eds.), February 1, pp. 23-37.

Wakamatsu, K., Yoshida, N., Suzuki, N., and Tazoh, T. (1992). "Liquefaction-induced large ground deformations and their effects on lifelines during the 1990 Luzon, Philippines earthquake." *Case Studies of Liquefaction and Lifeline Performance During Past Earthquakes, Volume 1: Japanese Case Studies, Tech. Rep. NCEER-92-0001*, M. Hamada and T. D. O'Rourke (eds.), February 17, 52 pages.

**B.14. 1991 Telire-Limon, Costa Rica, Earthquake . . . . . Slide Nos. 104 - 108.**

Earthquake Engineering Research Institute (1991). "Costa Rica earthquake of April 22, 1991, reconnaissance report: Chapter 6, Bridges" *Earthquake Spectra*, Suppl. B to Vol. 7, October.

Yoshida, N., Watanabe, H., Yasuda, S., and Mora, S. (1992). "Liquefaction-induced ground failure and related damage to structures during 1991 Telire-Limon, Costa Rica, earthquake." *Proc., 4<sup>th</sup> Japan-U.S. Workshop on Earthquake Resistant Design of Lifeline Facilities and Countermeasures for Soil Liquefaction, Tech. Rep. NCEER-92-0019*, M. Hamada and T. D. O'Rourke (eds.), August 12, pp. 37-52.

Youd, T. L., Rollins, K. M., Salazar, A. F., and Wallace, R. M. (1992). "Bridge damage caused by liquefaction during the 22 April 1991 Costa Rica earthquake." *Proc., 10<sup>th</sup> World Conf. Earthquake Engrg.*, pp. 153-158.

**B.15. 1993 Hokkaido Nansei-oki, Japan, Earthquake . . . . . Slide Nos. 109 - 117.**

Earthquake Engineering Research Institute (1995). "Hokkaido-Nansei-oki earthquake and tsunami of July 12, 1993, reconnaissance report" *Earthquake Spectra*, Suppl. A to Vol. 11, R. M. Chung (ed.), April.

Isoyama, R. (1994). "Liquefaction-induced ground failures and displacements along the Shiribeshi-toshibetsu River caused by the 1993 Hokkaido-nansei-oki earthquake." *Proc., 5<sup>th</sup> U.S.-Japan Workshop on Earthquake Resistant Design of Lifeline Facilities and Countermeasures Against Soil Liquefaction, Tech. Rep. NCEER-94-0026*, T. D. O'Rourke and M. Hamada (eds.), November 7, pp. 1-26.

Iwatate, T., Sawada, Y., Inoue, D., and Sakamoto, Y. (1994). "Characteristics and damage investigation of 1993 Hokkaido Nansei-oki earthquake." *Proc., 5<sup>th</sup> U.S.-Japan Workshop on Earthquake Resistant Design of Lifeline Facilities and Countermeasures Against Soil Liquefaction, Tech. Rep. NCEER-94-0026*, T. D. O'Rourke and M. Hamada (eds.), November 7, pp. 101-115.

Yanev, P. I., and Scawthorn, C. R. (1993). "Hokkaido Nansei-oki, Japan, earthquake of July 12, 1993." *Tech. Rep. NCEER-93-0023*, December 23.

**B.16. 1994 Northridge, California, Earthquake . . . . . Slide Nos. 118 - 121.**

Davis, C. A., and Bardet, J. P. (1994). "Geotechnical observations at the Van Norman Complex after the 1994 Northridge earthquake." *Proc., 5<sup>th</sup> U.S.-Japan Workshop on Earthquake Resistant Design of Lifeline Facilities and Countermeasures Against Soil Liquefaction, Tech. Rep. NCEER-94-0026*, T. D. O'Rourke and M. Hamada (eds.), November 7, pp. 63-77.

Goltz, J. D. (ed.) (1994). "The Northridge, California earthquake of January 17, 1994: General reconnaissance report." *Tech. Rep. NCEER-94-0005*, March 11.

Holzer, T. L., Bennett, M. J., and Tinsley, J. C., III, Ponti, D. J., and Sharp, R. V. (1996). "Causes of ground failure in alluvium during the Northridge, California, earthquake of January 17, 1994." *Proc., 6<sup>th</sup> Japan-U.S. Workshop on Earthquake Resistant Design of Lifeline Facilities and Countermeasures Against Soil Liquefaction, Tech. Rep. NCEER-96-0012*, M. Hamada and T. D. O'Rourke (eds.), September 11, pp. 345-360.

Stewart, J. P., Bray, J. D., Seed, R. B., and Sitar, N. (eds.) (1994). "Preliminary report on the principal geotechnical aspects of the January 17, 1994, Northridge earthquake." *Report No. UCB/EERC-94/08*, Earthquake Engineering Research Center, University of California, Berkeley, June, 245 pages.