

Table of Contents

(ABSTRACT)	I
ACKNOWLEDGMENTS	III
TABLE OF CONTENTS	IV
LIST OF FIGURES	VIII
LIST OF TABLES	IX
CHAPTER 1	1
INTRODUCTION	1
1.1 BACKGROUND	1
1.2 RESEARCH NEEDS	5
1.3 HYPOTHESIS	6
1.4 OBJECTIVES	6
1.5 SIGNIFICANCE	7
CHAPTER 2	8
LITERATURE REVIEW	8
2.1 STATUS OF AUTOMATION RESEARCH FOR FOREST PRODUCTS	8
2.1.1 <i>Optical</i>	8
2.1.2 <i>Ultrasound</i>	9
2.1.3 <i>Microwave</i>	9
2.1.4 <i>Nuclear Magnetic Resonance (NMR)</i>	10
2.1.5 <i>X-ray</i>	10
2.1.6 <i>Single-Sensor Scanning Methods</i>	11
2.1.7 <i>Multi-Sensor Scanning Methods</i>	11
2.1.8 <i>Economics of a Scanning System in Industry</i>	12
2.2 IMAGE PROCESSING METHODS	13
2.2.1 <i>Image Formation</i>	13

2.2.2 <i>Low-level methods</i>	14
2.2.3 <i>High-level methods</i>	16
2.3 DEFECTS IN WOOD	17
2.3.1 <i>Occurrence of Defects in Hardwood Lumber</i>	20
2.3.2 <i>Defect Parameters that can be Measured</i>	21
2.4 COLOR	21
2.4.1 <i>Color and the Illuminant</i>	23
2.4.2 <i>Color Spaces</i>	24
2.4.3 <i>Wood and Color</i>	24
2.4.3.1 <i>Variation between Species</i>	26
2.4.3.2 <i>Variation within Species</i>	27
2.4.3.3 <i>Color Parameters in Wood</i>	27
2.4.4 <i>Factors Affecting Wood Color</i>	28
2.4.4.1 <i>Moisture Content and Temperature</i>	28
2.4.4.2 <i>Exposure to ultraviolet light</i>	29
2.4.5 <i>Defects and Color</i>	29
2.5 DENSITY	31
2.5.1 <i>Density and X-ray attenuation</i>	31
2.5.2 <i>X-rays and Wood Density</i>	32
2.5.3 <i>Factors Affecting Wood Density</i>	33
2.5.4 <i>Defects and Density</i>	33
2.6 OBJECT SHAPE MEASURES	34
2.7 CONCLUDING REMARKS	35
CHAPTER 3	37
EXPERIMENTAL METHODS	37
3.1 OVERVIEW	37
3.2 MULTI-SENSOR VISION SYSTEM AT VIRGINIA TECH	37
3.3 SPECIMENS	44
3.4 MEASUREMENTS.....	49
3.5 REGIONAL SEGMENTATION AND DATA COLLECTION	49
3.6 DESCRIPTION OF WOOD FEATURES.....	50
3.6.1 <i>Checking in Knots</i>	50
3.6.2 <i>Effect of feature angle on regional x-ray attenuation measures</i>	53
3.6.3 <i>Anatomical description and feature subclasses</i>	56

3.6.3.1 <i>Red Oak</i>	59
3.6.3.2 <i>Maple</i>	61
3.6.3.3 <i>White Pine</i>	61
3.6.4 <i>Summary of Feature Descriptions</i>	61
3.6.5 <i>Determination of Feature Parameter Relationships</i>	62
3.6.6 <i>Modeling Wood Features Using Measured Parameters</i>	62
CHAPTER 4.....	65
DESCRIPTION AND COMPARISON OF WOOD FEATURE PARAMETERS	65
4.1 INTRODUCTION	65
4.2 PARAMETER DIFFERENCES BETWEEN FEATURES	65
4.2.1 <i>Red Oak</i>	67
4.2.2 <i>Hard Maple</i>	72
4.2.3 <i>White Pine</i>	75
4.2.4 <i>Summary of Parameter Differences between Features</i>	77
4.3 AFFECT OF SPECIES ON FEATURE PARAMETERS.....	78
4.3.1 <i>Color Parameters</i>	80
4.3.1.1 <i>RGB Color Parameters</i>	80
4.3.1.2 <i>HSI Color Parameters</i>	85
4.3.1.3 <i>Summary of Color Parameters</i>	87
4.3.1.4 <i>Feature Color Differences Related to Clearwood</i>	89
4.3.2 <i>Density Parameters</i>	91
4.3.3 <i>Shape Measures</i>	91
4.3.4 <i>Summary of Parameter Differences between Species</i>	93
4.4 EFFECT OF RESOLUTION ON FEATURE PARAMETERS	93
4.5 SUMMARY	94
CHAPTER 5.....	97
FEATURE CLASSIFICATION USING COLOR, SHAPE, AND DENSITY PARAMETERS	97
5.1 INTRODUCTION	97
5.2 DISCRIMINANT ANALYSIS DEFINED	98
5.3 VARIABLE SELECTION FOR DISCRIMINANT CLASSIFIERS.....	100
5.3.1 <i>Single Variable Discriminant Classifiers</i>	102

5.3.2 <i>Multi-variable Discriminant Classifiers</i>	106
5.3.2.1 <i>RGB Color Space Parameters</i>	106
5.3.1.2 <i>HSI Color Parameters</i>	111
5.3.4 <i>Summary of Classification Variables</i>	113
5.4 ABILITY OF PARAMETERS TO DIFFERENTIATE FEATURES IRRESPECTIVE OF SPECIES	117
5.4.1 <i>RGB Color Based Multi-species Classifier</i>	117
5.4.2 <i>HSI Color Based Multi-species Classifier</i>	119
5.4.3 <i>Summary of Multi-species Classifiers</i>	119
5.5.4 <i>Comparison of RGB and HSI Color Spaces</i>	119
5.6 CHAPTER SUMMARY.....	123
CHAPTER 6.....	124
SUMMARY AND CONCLUSIONS.....	124
6.1 SUMMARY	124
6.2 CONCLUSIONS.....	127
6.3 RECOMMENDATIONS FOR FUTURE RESEARCH	129
LITERATURE CITED.....	131
APPENDIX	142
VITA	160

List of Figures

Figure 2.1. Graphical representation of the RGB colorspace.....	25
Figure 2.2. Eccentricity measure defined A/B.....	34
Figure 3.1. Outline of experimental methods.....	38
Figure 3.2. Diagram of the sensor layout on the scanning system used to collect images...	40
Figure 3.3. Examples of red (a) green (b), blue (c), and x-ray (d) images	43
Figure 3.4. Example of AOI selected knot region for density parameter measure.....	51
Figure 3.5. Severe checking in a red oak knot	54
Figure 3.6. Effect of knot angle on x-ray attenuation images	55
Figure 3.7. Diagram of experimental data analysis	63
Figure 4.1. The mean and standard deviation for the I_m parameter measured in red oak (a), hard maple (b), and white pine (c).....	88

List of Tables

Table 2.1. Definition of defects based on NHLA grading rules (NHLA, 1996).....	19
Table 2.2. Frequency of defects in No1. and No.2 Common red oak as found by Widoyoko, (1996) and Buehemann (1997).....	22
Table 3.1. Differences in species used in experimental methods (Hoadley, 1990).....	45
Table 3.2. Definition of prevalent wood features included in this study	47
Table 3.3. Actual number of samples for each species and feature type.	48
Table 3.4. Definition of properties used to characterize wood features.....	52
Table 3.5. Individual measures used in ANOVA comparisons of feature measurement method.....	57
Table 3.6. Anatomical description of wood features.....	58
Table 3.7. Definitions of feature sub-classes for all species.....	60
Table 4.1. Definition of parameters used to characterize wood features.....	66
Table 4.2. Analysis of variance used for each parameter and species.....	68
Table 4.3. Parameters that have significant differences between features in red oak.....	69
Table 4.4. Significantly different parameters and their associated p-values for features in hard maple.....	73
Table 4.5. Significantly different parameters and their associated p-values for features in Eastern white pine.....	76
Table 4.6. Parameters suggested for use in differentiating between features for the each species.....	79
Table 4.7. Significant parameter differences between species for knots.....	81
Table 4.8. Significant parameter differences between species for bark pockets.....	82
Table 4.9. Significant parameter differences between each species for stain and mineral streak.....	83
Table 4.10. Significant parameter differences between species for clearwood.....	84
Table 4.11. Difference in clearwood mean color parameters for red oak, hard maple, and white pine.....	86
Table 4.12. Color parameters for each feature type that have a relationship to clearwood...	90

Figure 4.13. Ratio of knot to clearwood density for red oak, hard maple, and white pine...	92
Table 4.14. Difference between species knot x-ray attenuation.....	92
Table 4.15. P-values for significant differences between resolutions.....	95
Table 5.1. Classification results for each parameter for red oak features.....	103
Table 5.2. Classification results for each parameter for hard maple features.....	104
Table 5.3. Classification results for each parameter for white pine features.....	105
Table 5.4. The RGB color based parameters selected by the forward method, (F), backward method, (B), and from statistical relationships determined in Chapter 4, (S).	107
Table 5.5. HSI color based parameters selected by the forward method, (F), backward method, (B), and from statistical relationships determined in Chapter 4, (S).....	107
Table 5.6. RGB color based classification accuracies where F is the forward method, B is the backward method, A is all parameters, and S for parameters selected from parameter relationships determined in Chapter 4.....	110
Table 5.7. HSI color based classification accuracies where F is the forward method, B is the backward method, A is all parameters, and S for parameters selected from parameter relationships determined in Chapter 4.....	112
Table 5.8. Feature classes formed from subclasses for red oak.....	115
Table 5.9. Classification results for red oak original feature classes compared with combined subclasses as percent classified correctly for each species and color space.....	116
Table 5.10. Parameters selected for the RGB and HSI color based multi-species classifier for all species.	118
Table 5.11 Classification results presented as percent classified correctly for each species and color space for multi-species classifiers.....	120
Table 5.12 The classification results for RGB and HSI color based classifiers presented as percent classified correctly for each species and color space.....	122
Table 5.13. Parameters selected for the comparison of color spaces.....	122
Table 5.14. Classification results between color spaces using color parameters only.....	122
Table A1. Moisture content (MC) and specific gravity (SG) of selected samples for all species.....	142

Table A2. P-values for differences between oak knot classes for parameters	143
Table A3. P-values for differences between oak bark classes for parameters.	144
Table A4. P-values for differences between hard maple knot classes for parameters.....	145
Table A5. P-values for differences between white pine knot classes for parameters.....	146
Table A6. P-values for statistical differences for parameters between feature types for red oak.....	147
Table A7. P-values for statistical differences for parameters between feature types for red oak.....	148
Table A8. P-values for statistical differences for parameters between feature types for hard maple.....	149
Table A9. P-values for statistical differences for parameters between feature types for hard maple.	150
Table A10. P-values for statistical differences for parameters between feature types for white pine.....	151
Table A11. P-values for statistical differences for parameters between feature types for white pine.....	152
Table A12. P-values for significance of species*feature interactions for each parameter...	153
Table A13. P-values for parameter differences between species for knots.....	154
Table A14. P-values for parameter differences between species for bark pockets.....	155
Table A15. P-values for parameter differences between species for stain and mineral streak.....	156
Table A16. P-values for parameter differences between species for clearwood.....	157
Table A17. P-values for percent differences between clearwood and knot parameters for each species.....	158
Table A18. P-values for percent differences between clearwood and bark pocket parameters for each species.....	158
Table A19. P-values for percent differences between clearwood and stain/mineral streak parameters for each species.....	159

Table A20. P-values for percent differences for between clearwood and feature density for each species.....159