
APPENDIX E

MODAL TEST RESULTS- THREE SPAN FOOTBRIDGE

APPENDIX E MODAL TEST RESULTS- THREE SPAN FOOTBRIDGE




Stage 1: All Bottom Chord Extensions In Place




Stage 2: Exterior Bottom Chord Extensions Removed



Stage 3: All Bottom Chord Extensions Removed




Stage 4: Interior Bottom Chord Extensions Re-installed





Stage 5: All Bottom Chord Extensions Re-installed







Stage 1: All Bottom Chord Extensions in Place







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test2







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test3







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test4








Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test5


















Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test8







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test9













Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test11







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test12






Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test13







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test14




FRF= (Output=0.041692V) / (Input=0.2093V) = 0.1992 vs. 0.1992 from below !!!







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test15




FRF= (Output=0.096525V) / (Input=0.1411V) = 0.6841 vs. 0.6842 from below !!!







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test16





FRF= (Output=0.10504V) / (Input=0.1499V) = 0.7007 vs. 0.7006 from below !!!







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test17







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test18










FRF= (Output=0.034927V) / (Input=0.1792V) = 0.1949 vs. 0.195 from below !!!




467




Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test20


Test 20 was exactly the same as Test 19




Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test21




FRF= (Output=0.11868V) / (Input=0.1359V) = 0.8733 vs. 0.8734 from below !!!




Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test22




FRF= (Output=0.033124V) / (Input=0.1783V) = 0.1858 vs. 0.1857 from below




Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test23




FRF= (Output=0.071814V) / (Input=0.1754V) = 0.4094 vs. 0.4094 from below





Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test24







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test25






Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Test26







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 1




Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 2




Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 3





Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 4







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 5







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 6







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 7







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 8







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 9







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 10








Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 11















Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 13







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 14








Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 15
























Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 19















Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 21







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 22













Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 24







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 25







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 26







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 27







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 28







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 29







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 30







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 31







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 32







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 33







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 34







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 35







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 36













Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 38








Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 39





















Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 42







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 43








Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 44















Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 46







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 47







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 48







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 49







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 50







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 51







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 52







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 53







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 54






Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 55







Three Span Floor- Stage 1- All Bottom Chord Extensions in Place- Aug 4,2004, Test 56





Stage 2: Exterior Bottom Chord Extensions Removed








Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test1















Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 3







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 4







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 5







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 6







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 7







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 8







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 9a







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 9b







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 9c







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 10







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 11







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 12








Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 13















Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 14b







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 15








Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 16















Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 18








Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 19
























Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 22








Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 23















Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 25







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 26a







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 26b







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 27







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 28








It is exactly the same as 28















Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 31a







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 31b







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 32







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 33







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 34







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 35







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 36a







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 36b








Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 37
























Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 40















Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 41b







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 42











Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 44																								
	1	1		i		1		Π		:		i		:		Π		:		i		:		
0	0	Ó	0	Ŷ	0	Ó	0	Ŷ	0	ò	0	Ŷ	0	ò	0	P	0	Ó	0	Ŷ	0	Ó	0	0
10	0	ė	0	φ	0	ö	0	6	0	ò	0	_∕æ ⁸	0	ò	0	6	0	ö	0	Φ	0	ė	0	
				-								τ μι								-				
				ļ								2		3		4		5		6				7
	0	Ŷ	0	φ_	0	Ŷ	0		0	Ŷ	0	<u>\$</u>	0	×	0	<u>*</u>	0	×	0	來	0	Ŷ	0	<u>×</u>
L	1	i i		1		i				÷				i				i		i i		i		


Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 44


Test 44 was supposed to be 8.75 Hz Sine excitation. However, it was saved exactly the same as Test 45 which is a 9.85 Hz sine excitation.

See Test 45 below.













Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 46a








Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 46b
























Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 49







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 50







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 51







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 52








Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 53















Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 55







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 56







Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 57






Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 58






Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 59





Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 60




Three Span Floor- Stage 2- Exterior Bottom Chord Extensions Removed- Test 61


Stage 3: All Bottom Chord Extensions Removed







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 1







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 2







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 3















Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 5












Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 7



Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 8




Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 9




Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 10

Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 11 0 C C 0 0 0 ó 0 0 Ó 0 0 Ó 0 0 ò 0 0 0 0 0 ċ 0 Ó ¢ ×


Same as Test 10




Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 12









Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 14




Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 15































Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 19















Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 21







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 22







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 23







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 24







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 25







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 26







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 27







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 28































Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 32







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 33







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 34







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 35







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 36







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 37







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 38







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 39








Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 40
























Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 43







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 44







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 45







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 46







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 47







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 48







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 49







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 50







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 51







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 52







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 53














Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 55















Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 57







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 58







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 59







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 60







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 61








Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 62
























Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 65







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 66







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 67







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 68







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 69







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 70







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 71







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 72















Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 74







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 75







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 76







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 77















Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 79















Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 81







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 82







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 83















Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 85








Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 86























Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 89







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 90







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 91








Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 92















Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 94







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 95







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 96







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 97








Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 98























Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 101







Three Span Floor- Stage 3- Interior Bottom Chord Extensions Removed- Test 102




Stage 4: Interior Bottom Chord Extensions Re-installed


Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 127










Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 128








Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 129















Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 131







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 132







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 133








Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 134















Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 136








Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 137


































Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 141














Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 143





Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 144







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 145








Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 146
















Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 148















Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 150








Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 151














Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 153







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 154




(Channel 5 bad)





Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 155






Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 156







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 157




(Channel 5 bad)





Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 158






Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 159







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 160




(Channel 5 bad)





Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 161







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 162








Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 163















Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 165







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 166








Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 167















Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 169







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 170







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 171










Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 172







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 173







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 174







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 175








Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 176















Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 178





Frequency Response Functions: Magnitude





















Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 181







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 182







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 183







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 184







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 185







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 186








Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 187















Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 189








Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 190















Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 192







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 193








Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 194
















Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 196

























Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 199















Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 201







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 202







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 203







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 204







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 205






Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 206








Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 207





(Channel 5 bad)





















Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 210







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 211







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 212








Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 213















Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 215







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 216







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 217







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 218







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 219






Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 220







Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 221



Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 222



Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 223



Three Span Floor- Stage 4- Interior Bottom Chord Extensions Re-installed- Test 224